	1		
4	1		
	ı		

Facility name:	Pasco Sanitary Landfill
Location:	Pasco, Washington
EPA Region:	10
*	ge of the facility: Larry Dietrich
Porson(a) in one	
***	
Name of Review	Lynn Guilford Date: 547/87
General descrip	on of the facility:
facility; contami	ation route of major concern; types of information needed for rating; agency action, etc.)
Resource	Recovery Corporation operated a portion of Pasco Landfill as a hazardous waste disposal site
from 1972	to 1974. Currently the disposal areas are all
covered v	ith three feet of soil. This cover gives both
the surfa	ce water and direct contact routes scores of
O. The	round water route has an observed release and
a large	round water population giving the site an
1 1 1	
overall s	core of 44.46
overall	core of 44.46
overall s	core of 44.46
overall s	core of 44.46

FIGURE 1 HRS COVER SHEET

Scores:  $S_M = 44.46 \ (S_{gW} = 76.92 \ S_{SW} = 0 \ S_a = 0)$ 

 $s_{FE} = 0$  $s_{DC} = 0$ 

Markey & Son & Son & Son & Markey & Markey & Son & Son & Son & Son & Son & Markey &



		<del></del>	Ground	Wate	r Route Work S	Sheet				
	Rating Factor			-	d Value One)		Multi- plier	Score	Max. Score	Ref. (Section)
0	Observed Release		0		<b>4</b> 5		1	45	45	3.1
	If observed release									=:
2	Route Characterist Depth to Aquifer		0	1 2	3		2		6	3.2
	Concern Net Precipitation Permeability of the	he		1 2	3 3		1		3 3	
	Unsaturated Zo Physical State	ne	0	1 2	3		1		3	<del></del>
			Total Rout	e Cha	racteristics Sco	ore			15	<del></del>
3	Containment	,	0	1 2	3		1		3	3.3
4	Waste Characteris Toxicity/Persiste Hazardous Wast Quantity	ence		3 6 1 2	9 (12)15 18 3 4 5 6	7 (8)	1 1	12 8	18 8	3.4
	ı		Total Was	te Chi	aracteristics Sc	ore		20	26	
5	Targets Ground Water U Distance to Nea Well/Population Served	rest	0 0 12 24	4 16 1	2 ③ 6 8 10 8 20 2 35 40		3	9 40	9 40	3.5
	•	<del></del>			rada Saara		<u> </u>	4.0	49	]
(R)					gets Score			49		
<u>6</u>			1 x 4 2 x 3		] × 5			44100	57.330	<u> </u>
7	Divide line 6 b	by 57,330	and multip	ly by	100		s <sub>gw</sub> =	76.	<b>~9</b> ′2	

FIGURE 2
GROUND WATER ROUTE WORK SHEET

John Bold

Surface Water Route Work Sheet							
Rating Factor	Assigned (Circle		Multi- plier	Score	Max. Score	Ref. (Section)	
1 Observed Release	0	45	1		45	4.1	
If observed release is give	n a value of 45, pi in a value of 0, pro	roceed to line [	<b>ā</b> ]. ].				
2 Route Characteristics				<del></del>		4.2	
Facility Slope and Interv	ening (0) 1 2	3	1		3		
1-yr. 24-hr. Rainfall	(D) 1 2	3	1 2		3 8		
Distance to Nearest Sur Water	(ace (1) 1 2	3	1		3		
Physical State					4.6		
	Total Route Cha	racteristics Scor	e 	_0	15		
3 Containment	<b>1</b> 2	3	1	0	3	4.3	
4 Waste Characteristics Toxicity/Persistence Hazardous Waste Quantity	© 3 6 ⑤ 1 2	9 12 15 18 3 4 5 6 7	1 8 1	0	18 8	4.4	
	Total Waste Che	aracteristics Sco	re	0	28		
				<del></del>		4.5	
5 Targets Surface Water Use	<b>(a)</b> 1	2 3	3	0	9 8		
Distance to a Sensitive Environment		2 3	2	0	40		
Population Served/Dist to Water Intake Downstream	ance 0 4 12 16 24 30	6 8 10 18 20 32 35 40	•	U	40		
Total Targets Score 0 55							
6 If line 1 is 45, multiply	ly 1 x 4 x [ , 2 x 3 x 4				64,350		
7 Divide line 6 by 64,3	50 and multiply by	100	Saw	- 0 '	्यक्षी हैं । H केर्र प्रकेश		

FIGURE 7
SURFACE WATER ROUTE WORK SHEET

Modfa 7-17-87

Air Route Work Sheet							
	Rating Factor	Assigne (Circle		Multi- plier	Score	Max. Score	Ref. (Section)
1	Observed Release	0	45	1	0	45	5.1
	Date and Location:				<u></u>		
	Sampling Protocol:						
If line 1 is 0, the S <sub>a</sub> = 0. Enter on line 5.  If line 1 is 45, then proceed to line 2.							
2	Waste Characteristics Reactivity and	0 1 2	3	1		3	5.2
	incompatibility Toxicity Hazardous Waste Quantity	0 1 2 0 1 2	3 3 4 5 6	3 7 8 1		9 8	
						20	
		Total Waste Ch	aracteristics Sco	ore	·	20	
3	Population Within	) 0 9 12 21 24 27	15 18	1		30	5.3
	4-Mile Radius Distance to Sensitive Environment	0 1 2	3	2		6	
	Land Use	0 1 2	3	1		3	
	•						
		Total Ta	irgets Score			39	}
14	Multiply 1 x 2 x	(3)				35,100	
5	Divide line 4 by 35	,100 and multiply by	100	Sa=	0	Select <sub>co.</sub>	

FIGURE 9 AIR ROUTE WORK SHEET health told

	s	s²
Groundwater Route Score (Sgw)	76.92	5916.69
Surface Water Route Score (S <sub>SW</sub> )	0	0
Air Route Score (Sa)	0	0
$s_{gw}^2 + s_{sw}^2 + s_a^2$		5916.69
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2}$		76.92
$\sqrt{s_{gw}^2 + s_{sw}^2 + s_a^2} / 1.73 - s_M =$		44.46

FIGURE 10 WORKSHEET FOR COMPUTING S<sub>M</sub>

Modelle

Fire and Explosion Work Sheet															
Rating Factor Assigned Value Multi- (Circle One) Multi- plier Score Score								Ref. (Section)							
1	Containment		1					3				1		3	7.1
2	Waste Characterist	lics													7.2
	Direct Evidence		O			3						1		3	
	Ignitability		0	-	_							1		3	
	Reactivity		0		2	3						1		3 3	
	Incompatibility Hazardous Waste Quantity		O					5	6	7	8	1		8	
			Total Wa	ste	Ch	ara	cter	istic	:8 5	Scor	<u> </u>			20	<del></del>
3	Targets				•				i				<u></u>	<del></del>	7.3
	Distance to Neare	est	O	1	2	3	4	5				1		5	
	Distance to Neare Building	est	·	1	2	3						1		3	
	Distance to Sensi	tive	C	1	2	3						1		3	
	Land Use		C	1	2	3						1		3	
	Population Within 2-Mile Radius		C	1	2	3	4	5				1		5	
	Bulldings Within 2-Mile Radius		, (	1	2	3	4	5				1		5	
_												-		<del>,</del>	1
			T	ota	Та	rge	ts S	cor	е					24	<u> </u>
4	Multiply 1 x 2	x 3												1,440	
5	Divide line 4 by	y 1,440 a	ind multip	oly	by	100						SFE =	0		

FIGURE 11
FIRE AND EXPLOSION WORK SHEET

Madla Des

	Direct Contact Work She	et			
Rating Factor	Assigned Value (Circle One)	Multi- plier	Score	Max. Score	Ref. (Section)
① Observed incident	0 45	1		45	8.1
	oceed to line 4 ceed to line 2				
2 Accessibility	0 ① 2 3	1	1	3	8.2
3 Containment	<b>(</b> ) 15	1	0	15	8.3
Waste Characteristic	<b>(6)</b> 1 2 3	5	0	15	8.4
Targets Population Within a	<b>1</b> 2 3 4 5	4	0	20	8.5
1-Mile Radius Distance to a Critical Habitat	<b>1</b> 2 3	4	0	12	
			·.		٦
. [	Total Targets Score		0	32	
6 If line 1 is 45, 1	multiply 1 × 4 × 5 nultiply 2 × 3 × 4 × 5		0	21,600	
	y 21,600 and multiply by 100	SDC	- 0		

FIGURE 12 DIRECT CONTACT WORK SHEET Anothan Palar



# ecology and environment, inc.

101 YESLER WAY, SEATTLE, WASHINGTON, 98104, TEL. 206/624-9537

International Specialists in the Environment

DOCUMENTATION RECORDS

FOR

HAZARD RANKING SYSTEM

Instructions: The purpose of these records is to provide a convenient way to prepare an auditable record of the data and documentation used to apply the Hazard Ranking System to a given facility/site. As briefly as possible summarize the information you used to assign the score for each factor (e.g., "Waste Quantity = 4320 drums plus 800 cubic yards of sludges"). The source of the information should be provided for each entry and should be a biographical-type reference that will make the source used for the data point easier to find. Include the location of the source and consider appending a copy of the relevant page(s) for ease in review.

FACILITY NAME: Pasco Sanitary Landfill

LOCATION: Kahlotus Road and Highway 12

Pasco, Washington 99301

REVIEWER: Lynn Guilford

TDD: TDD F10-8701-04

ECOLOGY AND ENVIRONMENT, INC.

DATE: June 1987

Madrid By

#### GROUND WATER ROUTE

- 1. OBSERVED RELEASE
- 1a. Contaminants Detected (5 maximum) in Ground Water

Tetrachloroethylene was found in monitoring well EE2.

Trichloroethylene was found in monitoring wells EE2, EE3, and JUB 2.

The levels found were significantly over background (JUB-CNTR)

- Rationale for attributing the contaminants to the facility:

These compounds, tetrachloroethylene and trichloroethylene, were not found in background wells, but were only found in wells downgradient and adjacent to zone A and the old landfill burn and demolition disposal area. Paint wastes were disposed in Zone A.

HRS Section Score: 45 (Ref. 1 p.s.o)

\* \* \* \* \* \* \* \* \*

- 2. ROUTE CHARACTERISTICS
- 2a. Depth to Aquifer of Concern
  - Name and description of aquifer(s) of concern:

    Water table aquifer, unconfined, which overlies

    Vakima Basalts, broundwater occurs 3315 to 68.7 feet
    below ground surface at site. See table 4.1 and figures

    His and 413 of Reference I for description of geologic

    units and cross-sections.

HRS Section Score: (Ref.

- 2b. Net Precipitation
  - Mean annual or seasonal precipitation (list months for seasonal):
  - Mean annual lake evaporation rate (list months for seasonal):
  - Net precipitation (subtract above figures):

HRS Section Score: (Ref.

Made 17 8

The refined by the billing the december 1	2c.	Permeabili	tv o	f Unsa	aturated	Zone
---	-----	------------	------	--------	----------	------

- Soil type in unsaturated zone:
- Permeability associated with soil type:

HRS Section Score: (Ref. )

#### 2d. Physical State

- Physical state of substance at time of disposal (or at present time for generated gases):

HRS Section Score: (Ref. )

· \* \* \* \* \* \* \* \*

- 3. CONTAINMENT
- 3a. Containment
  - Method(s) of waste or leachate containment evaluated:
  - Method with highest score:

HRS Section Score: (Ref. )

\* \* \* \* \* \* \* \* \*

- 4. WASTE CHARACTERISTICS
- 4.a Toxicity and Persistence
  - Compound(s) evaluated:

Compound	Toxicity	Persistence	Tota1	Ļ
Trichloroethylene Tetrachloroethylene	2 2	2 2	12 12	

- Compound(s) with highest score:

Tetrachloroethylene and Trichloroethylene

HRS Section Score: 12 (Ref. 2

) Jordin

### 4b. Hazardous Waste Quantity

- Total amount of hazardous substance at the facility, excluding those with a containment score of zero. (Give a reasonable estimate, even if the quantity is above maximum.):

The total waste quantity is estimated to be approximately 47,000 drums.

- Basis of estimating and/or computing waste quantity (must be documented quantity and not assumed):

Paint Wastes - 26,426 drums 2,4-D Mfg. wastes - 5,080 drums Carcinogenics - 9 drums Aromatic Tar -1,159 drums Cadmium Waste - 11 drums Pesticides - 425 drums
Metal Finishing/Cleaning
- 10,947 drums
Solvents - 253 drums
Barium with Mercury
- 2,896 drums

HRS Section\_Score: 8 (Ref. 1,3,4,5)

\* \* \* \* \* \* \* \* \*

#### 5. TARGETS

### 5a. Ground Water Use

- Use(s) of aquifer(s) of concern within a 3-mile radius of the facility:

Ground water is used for drinking water and irrigation within three miles of the site. Some of the wells used for drinking water are beyond the perimeter of the public water supply system.

HRS Section Score: 3 (Ref. 6,7,8, 9,10,11,12,13)

## 5b. Distance to Nearest Well

- Location of nearest well drawing from the "aquifer of concern" or occupied building not served by a public water supply:

SW 1/4, NW 1/4, Section 22, Township 9N, Range 30E.

- Distance from site to above well or building:

The well is on site, approximately 800 feet north of monitoring wells EE2, EE3, and JUB 2, which are contaminated.

HRS Section Score: 4 (Ref. 11,13 )

# 5c. Population Served by Ground Water within a 3-Mile Radius

- Identify water supply well(s) drawing from the "aquifer of concern" within a 3-mile radius and populations served by each:

See sheet 4A Todal 1048

- Compute land area irrigated by supply well(s) drawing from the "aquifer of concern" and convert to population (1.5 people per acre):

See Sheets 4B,C,D

- Total population served by ground water:

1048+ 14820= 15868

HRS Section Score: 40 (Ref. 7,8,9, 10,11,12,13,14)

Hard And Standard

# Pasco Sanitary Landfill

6/5/87

Name  1. Weshington Idaho Laborers  2. Paul Sauge  3.8  7  2. Al lenney  3.8  7  3.8  7  4. Tom Kidwell  3.8  7  6. Lakeview Mobile Home Park  7. Rada Sons  16  8  1. Bohne Brae Trailer Court  12. De Vries Water system  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmusen  20. Western Farm Services  21. Frontier Machinery  3.8  10  3.8  10  3.8  10  3.8  10  3.8  10  3.8  10  3.8  10  3.8  3.8  40  40  40  40  40  40  40  40  40  4	GW used for dru	iting water	within 3 miles o	fabre site
1. Washington Idaho Laborers 3.8 7 2. Paul Sauage 3.8 7 3. Al Jenney 3.8 7 4. Tom Kidwell 3.8 7 5. Van Wormer 3.8 7 6. Lakeview Hobik Home Park 800 8 7. Rada Sons 16 8 10. BPA - Franklin 16 8 11. Bohne Brae Trailor Court 65 8 12. De Vries Water system 12 8 13. Palmarez 3.8 10 14. Marquez 3.8 10 15. Johnson & Boxbaum 3.8 10 16. Bumgarher 3.8 10 17. Dall 3.8 10 18. Cunningham 3.8 10 19. Rasmussen 3.8 10 19. Rasmussen 3.8 10 20. Western Farm Services 24 8 21. Frontier Machinery 50 8		Pop Served	Reference #	
2. Paul Sauage 3.8 7 2. Al Venney 3.8 7 4 Tom Kidwell 3.8 7 5. Van Wormer 3.8 7 6. Lakeview Mobile HomePark 800 8 7. Rada Sons 16 8 10. BFA - Franklin 16 9 11. Bonne Broe Trailor Court 65 8 12. De Vries Water system 12 8 13. Palmarez 3.8 10 14. Marquez 3.8 10 15. Johnson & Boxbaum 3.8 10 16. Bumgarner 3.8 10 17. Dall 3.8 10 18. Cunningham 3.8 10 19. Rasmussen 3.8 10 20. Western Farm Services 24 8 21. Frontier Machinery 50 8			7	
4 Ton Kidwell 3.8 7  4 Ton Kidwell 3.8 7  5. Van Wormer 3.8 7  6. Lakeview Mobile Home Park 800 8  7. Rada Sons 16 8  10. BPA - Franklin 16 9  11. Bohne Brae Trailer Court 65 8  12. De Vries Water system 12 8  13. Palmarez 3.8 10  14. Marquez 3.8 10  15. Johnson & Boxbaum 3.8 10  16. Bumgarher 3.8 10  17. Dall 3.8 10  18. Cunningham 3.8 10  19. Rasmussen 3.8 10  20. Western Farm Services 24 8  21. Frontier Machinery 50 8	2 Paul Squage	3.8	7	
4 Tom Kidwell 3.8  5. Van Wermer 3.8  6. Lakeview Mobile Home Park 800  7. Rada Sons 16  8  4. AZTIAN Construction Inc 20  10. BPA - Franklin 16  11. Bohne Brae Trailer Court 65  12. De Vries Water system 12  13. Palmarez 3.8  14. Marquez 3.8  15. Johnson & Boxbaum 3.8  16. Bumgarher 3.8  10  16. Bumgarher 3.8  10  16. Cunningham 3.8  10  18. Cunningham 3.8  10  19. Rasmussen 3.8  20. Western Farm Services 24  21. Frontier Machinery 50  1048.6	2 Al Yenney	3,8	7	
5. Van Wormer  6. Lakeview Mobile Home Park  7. Rada Sons  16  8  17. Rada Sons  18  19. BPA - Franklin  10. BPA - Franklin  11. Bohne Brae Trailer Court  12. De Vries Water System  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmusen  20. Western Farm Services  21. Frontier Machinery  10. 1048.6	4 Tom Kidwell	3.8	7	
G. Leteview Mobile HomePark 800  7. Rada Sons  16  8  1. Rada Sons  16  8  10. BPA - Franklin  11. Bonne Brae Trailer Court 65  12. De Vries Water system  13. Palmarez 3.8  14. Marquez 3.8  15. Johnson & Boxbaum 3.8  16. Bumgarher 3.8  17. Dall 3.8  19. Cunningham 3.8  19. Rasmussen 3.8  20. Western Farm Services 24  21. Frontier Machinery 50  8	5. Veh Wormer	3.8	7	
7. Rada Sons  16  8  9. AZTLAN Construction Inc. 20  10. BPA - Franklin  11. Bonne Brae Trailer Court  12. De Vries Water system  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  10  11  11  12  13  14  15  16  17  18  10  10  10  10  10  10  10  10  10	6. Lakeview Mobile Home Park	800	8	
9. AZTLAN Construction Inc 20  10. BPA - Franklin 16  11. Bonne Brae Trailer Court 65  12. De Vries Water system 12  13. Palmarez 3.8  14. Marquez 3.8  15. Johnson & Boxbaum 3.8  16. Bumgarner 3.8  17. Dall 3.8  18. Cunningham 3.8  19. Rasmussen 3.8  20. Western Farm Services 24  21. Frontier Machinery 50  8		16	8	
10. BPA. Franklin  11. Bonne Brae Trailer Court  12. De Vries Water system  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  10. Bussen  10. Bussen  3.8 10. Busse				•
10. BPA - Franklin  11. Bonne Brae Trailer Court  12. De Vries Water system  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  10. 8	q, AZTLAN Construction Inc	20	8	
11. Bonne Brae Troller Court 65  12. De Vries Water system 12  13. Palmarez 3.8  14. Marquez 3.8  15. Johnson & Boxbaum 3.8  16. Bumgarner 3.8  17. Dall 3.8  19. Cunningham 3.8  19. Rasmussen 3.8  20. Western Farm Services 24  21. Frontier Machinery 50  8		16	8	
12. De Vries Water system  13. Palmarez  14. Marquez  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  8	11. Bonne Brae Trailer Court	65	8	
13. Palmarez  14. Marquez  15. Johnson & Boxbaum  16. Bumgarner  17. Dall  18. Cunningham  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  10. 10. 10. 10. 10. 10. 10. 10. 10. 10.		15	8	
14. Marquez 15. Johnson & Boxbaum 3.8 10 16. Bumgarner 3.8 10 17. Dall 3.8 10 18. Cunningham 3.8 10 19. Rasmussen 3.8 20. western Farm Services 21 21. Frontier Machinery 8	13. Palmarez	3. g	10	
16. Bumgarner 17. Dall 18. Cunningham 19. Rasmussen 3.8 10 20. Western Farm Services 21. Frontier Machinery 8		3,8	10	
16. Bumgarner 17. Dall 18. Cunningham 19. Rasmussen 3.8 10 20. Western Farm Services 21. Frontier Machinery 8	15. Johnson & Boxbaum	3 ,8	* <u>.</u>	
17. Dall  18. Cunningham.  19. Rasmussen  20. Western Farm Services  21. Frontier Machinery  8		3,8		
18. Cunningham  19. Rasmussen  3.8  10  20. Western Farm Services  21. Frontier Machinery  8		3,8		
19. Rasmussen 3.8  20. Western Farm Services 21. Frontier Machinery 50 8	1 -	3,8	10	
20. Western Farm Services 24 8 21. Frontier Machinery 50 8	<b>9</b>	3.8	10	
21. Frontier Machinery 50		24	8	
+ 1 1048.6		50	8	
	,	1048.6	. विकास विकास	Dol

Hart About

# Pasco Santary Landfill

4B 6/10/87

EW wed for irrigation		les of above site:
Name	Acres	Reference #
Burlington Northern	290	9
- <b>N</b>	130	
Conn Mut Life Ihs	145	
Burlington Northern	290	·
	290	
"	300	
Middleton	142	
11	90	<b>i</b>
Columbia East	268	
Burlington Northern	137	
<b>5</b> 11	160	
· u	400	
11	315	
	107	
11	<b>७०</b> ६	
II.	200	
Sullivan	.70	
Burlington Northern	107	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	300	
11	40	
Alderson	120	
columbia East	200	
Burlington Northern	315	
Ti di	40	A ALAD P
,,	75	Leading 187
H11/	15	
USCE	(0	' ♦

Standard Oil	.75
Minnahah	40
Conn Mut Life Ins	137
	135
T, p, pett	160
Conn Mut Life Ins.	160
Worsham	157
Cox	157
II	5
Cohn Mut Life Ins	130
11	155
Worsham	157
Burlington Northern	480
WA ST DNR	520
Columbia East	130
Builington Northern	130
Seattle Hardware	4
clase	i
Modd	à
Fanning	7
Frontier Machinery	12.5
Pasco, City of	15
Columbia	268
Dietrich	38
tomlinson	345
Palomarez	26
Burden	<b>20</b>
Eastern Wa ID	5
Spooner	1
Reisinger	2
<b>)</b>	•

Harrion Fold

Reisinger		6,5		9
Reisinger Mann		10		
Johnson		515		
Lourdes		15		
Pasco, City of Pasco, Port of		10		
Pasco, Port of		3		
Columbia East		495		İ
Story		73		
H1111		20		
USCE	-	100		$\mathbf{V}$
	Total o	271,75	acres	4
		X 1.5	people p	er acie
	1	4820	people	

Wheel Stables

#### SURFACE WATER ROUTE

- 1. OBSERVED RELEASE
- 1a. Contaminants Detected in the Surface Water at the Facility or Down Gradient from It (5 maximum)

No observed release.

- Rationale for attributing contaminants to the facility:

HRS Section Score: (Ref.

\* \* \* \* \* \* \* \* \*

- 2. ROUTE CHARACTERISTICS
- 2a. Facility Slope and Intervening Terrain
  - Average slope of facility/site in percent:

The site is relatively flat (less than 1%).

- Name description of nearest down-slope surface water:

The only down slope water within two miles is a man-made dairy pond.

 Average slope of terrain between facility and above-cited surface water body in percent:

The average slope is less than 1%.

- Is the facility located either totally or partially in surface water? Yes / No (circle one)
- Is the facility completely surrounded by areas of higher elevation? Yes  $/ \underline{\text{No}}$  (circle one)

HRS Section Score: 0 (Ref. 1,12,13)

2b. 1-Year 24-Hour Rainfall in Inches

Less than 0.75

HRS Section Score: 0 (Ref. 2

White h

### 2c. Distance to Nearest Down-slope Surface Water

The man-made dairy pond is approximately 1,500 feet southwest of the site. No natural water is located within two miles of the site.

HRS Section Score: 0 (Ref. 1,12,13, 15,16)

### 2d. Physical State of Substance at Time of Disposal

No known waste is available to surface water migration.

HRS Section Score: 0 (Ref. 1 )

\* \* \* \* \* \* \* \* \* \*

- 3. CONTAINMENT
- 3a. Containment
  - Method(s) of waste or leachate containment:

All known hazardous wastes have been covered,

- Method with highest score:

All known hazardous wastes are covered with three feet of soil, four mil polyethylene sheeting, and capped with an additional two feet of soil.

HRS Section Score: 0 (Ref. 1 )

\* \* \* \* \* \* \*

- 4. WASTE CHARACTERISTICS
- 4a. Toxicity and Persistence
  - Compound(s) evaluated:

Compound	Toxicity	Persistence	Total	1
				par .
			1	

Macha Balal

- Compound(s) with highest score:

No known compounds are available to migration.

HRS Section Score: 0 (Ref. 1 )

#### 4b. Hazardous Waste Quantity

- Total amount of hazardous substance at the facility/site, excluding those with a containment score of zero. (Give a reasonable estimate, even if the quantity is above maximum.):

No known waste is available to surface water migration.

- Basis of estimating and/or computing waste quantity (must be documented and not assumed):

HRS Section Score: 0 (Ref. 1

\* \* \* \* \* \* \* \* \*

#### 5. TARGETS

#### 5a. Surface Water Uses

- Use(s) of surface water within 3-miles downstream of the hazardous substance:

No natural surface water is used within two miles of the site and no known hazardous wastes are available to migration.

- Is there tidal influence?

Yes / No (circle one)

HRS Section Score: (Ref. 1

## 5b. Distance to Sensitive Environment

- Distance to 5-acre (minimum) coastal wetland, if 2 miles or less:
- Distance to 5-acre (minimum) fresh-water wetland, if 1 mile or less:
- Distance to critical habitat of federal endangered species or national wildlife refuge, if 1 mile or less:

HRS Section Score: 0 (Ref. 1

### 5c. Population Served by Surface Water

- Location(s) of water-supply intake(s) within 3 miles (free-flowing bodies) or 1 mile (static bodies) downstream of the hazardous substance and population served by each intake:

No known wastes are available to surface water. No natural surface water is located within two miles of the site.

- Compute land area irrigated by above-cited intake(s) and convert to population (1.5 people per acre):
- Total population served: 0
- Name and description of nearest above-cited water bodies:
- Distance from probable point of entry to above-cited intakes (stream miles):

HRS Section Score: 0 (Ref. 1,12,13, 15,16)

\* \* \* \* \* \* \* \* \*

Mad Market

# AIR ROUTE

1.	OBSERVED RELEASE	
1a.	Contaminants Detected in Ambient Air	
	None observed.	
-	Date and location of detection of contaminants:	
-	Method used to detect contaminants:	
-	Rationale for attributing contaminants to the site:	
	HRS Section Score: 0 (Ref. 1,15	)
	* * * * * * * *	i
ģ	WASTE CHARACTERISTICS	•
_		
	Reactivity and Incompatibility	
-	Most reactive compound:	
-	Most incompatible pair of compounds:	
	HRS Section Score: (Ref.	)
2b.	Toxicity	
-	Most toxic compound:	
	Compound Toxicity .	
	HRS Section Score: (Ref.	)
2¢.	Hazardous Waste Ouantity	

- Total quantity of hazardous waste at the facility/site:

- Basis of estimating and/or computing waste quantity:					
HRS Section Score: (Ref. )					
* * * * * * *					
S. TARGETS					
a. Population Within 4-mile Radius					
- Enter data under respective radius and indicate how determined:					
0 to 4 miles 0 to 1 mile 0 to 1/2 mile 0 to 1/4 mile					
HRS Section Score: (Ref. )					
Bb. Distance to Sensitive <u>Environment</u>					
- Distance to 5-acre (minimum) coastal wetlands, if 2 miles or less:					
- Distance to 5-acre (minimum) fresh-water wetland, if 1 mile or less:					
- Distance to critical habitat of an endangered species, if 1 mile or less:					
HRS Section Score: (Ref. )					
3c. <u>Land Use</u>					
- Distance to commercial/industrial area, if 1 mile or less:					
nt to the section of an extensive forest on wildlife meconys if 2					
<ul> <li>Distance to national or state park, forest, or wildlife reserve, if 2 miles or less:</li> </ul>					
Distance to weekdential among if 2 miles on less:					
- Distance to residential area, if 2 miles or less:	١				
- Distance to agricultural land in production within past 5 years, if 1 mile or less:	!				

- Distance to prime agricultural land in production within past 5 years, if 2 miles or less:
- Is a historic or landmark site (National Register of Historic Places and National Natural Landmarks) within the view of the site:

HRS Section Score:

(Ref.

Hoothan Doon

# FIRE AND EXPLOSION

FIRE	MARSHAL'S STATEMENT:			
	This site poses no fire/explosive	e potential (Ref. 16).		
1.	CONTAINMENT			
-	Hazardous substance present:			
-	Type of containment, if applicab	le:		
		HRS Section Score:	(Ref.	)
	* * * * * *	* * *		
2.	WASTE CHARACTERISTICS			
2a.	Direct Evidence			•
-	Type of Instrument and Measuremen	nt:		
		HRS Section Score:	(Ref.	)
2b.	Ignitability			
-	Compound considered:			
		HRS Section Score:	(Ref.	)
2c.	Reactivity			
-	Most reactive compound:	·		
	·	HRS Section Score:	(Ref.	)
2d.	Incompatibility			
_	Most incompatible pair of compou	nds:	. 65 <sup>7 г.</sup> 2185 <sup>г.</sup>	
		HRS Section Score:	(Ref.	

2e. <u>Hazardous Waste Quantity</u>			
- Total quantity of hazardous subs	tance(s) at the facility	/site:	
- Basis for estimating and/or comp	outing waste quantity:		
	HRS Section Score:	(Řef.	)
* * * * * *	* * * *		
3. TARGETS			
3a. Distance to Nearest Population			
	HRS Section Score:	(Ref.	)
3b. Distance to Nearest Building			•
	HRS Section Score:	(Ref.	)
3c. Distance to Nearest Sensitive En	<u>nvironment</u>		
- Distance to wetlands:			
- Distance to critical habitat:			
,	HRS Section Score:	(Ref.	,
3d. <u>Land Use</u>			
- Distance to commercial/industri	al area, if $1$ mile or les	ss:	
<ul> <li>Distance to national or state parties or less:</li> </ul>	ark, forest, or wildlife	refuge, if 2	

- Distance to residential area, if 2 miles or less:

- Distance to agricultural land in production within past 5 years, if 1 mile or less:

-	Distance to prime agricultural 1 if 2 miles or less:	and in production within	past 5 years,	•
-	Is a historic or landmark site w	ithin view of the site? Yes / No (circl	e one)	
	·	HRS Section Score:	(Ref.	)
3e.	Population Within 2-Mile Radius			
		HRS Section Score:	(Ref.	)
3f.	Buildings Within 2-Mile Radius			
		HRS Section Score:	(Ref.	)

photos photos

#### DIRECT CONTACT

- 1. OBSERVED INCIDENT
- la. Date, Location, and Pertinent Details of Incident

No observed incident reported.

HRS Section Score: 0 (Ref. 1,15 )

\* \* \* \* \* \* \* \* \* \*

- 2. ACCESSIBILITY
- 2a. Describe Type of Barrier(s)

Site is not fenced. However, the operator's residence is on site.

HRS Section Score: 1 (Ref. 17

\* \* \* \* \* \* \* \* \*

- 3. CONTAINMENT
- 3a. Type of Containment, if Applicable

The known hazardous waste is covered with three feet of soil, four mil polyethylene sheeting, and capped with an additional two feet of soil.

HRS Section Score: 0 (Ref. 1 )

\* \* \* \* \* \* \* \* \* \*

- 4. WASTE CHARACTERISTICS
- 4a. Toxicity .
  - Compounds evaluated:

Compound Toxicity
No compounds available for contact.

- Compound with highest score:

HRS Section Score: 0 (Ref. 1 )

\* \* \* \* \* \* \* \* \*

- 5. TARGETS
- 5a. Population Within 1-mile Radius of Site

No compounds available for contact.

HRS Section Score: (Ref. 1)

5b. Distance to Critical Habitat (of Endangered Species)

HRS Section Score: (Ref. )

\* \* \* \* \* \* \* \* \*

Machine Freder

#### REFERENCES

- 1. Ecology and Environment, Inc., June 1986. Final Report for Resource Recovery Corporation, Pasco, Washington.
- 2. U.S. Environmental Protection Agency (USEPA), 1984, <u>Uncontrolled Hazardous Waste Site Ranking System</u>, A <u>User's Manual</u>, 47FR 31220-31241.
- 3. Kimberly Jr., John R., President, Resource Recovery Corporation, July 2, 1980. Letter to Department of Ecology.
- 4. Washington Department of Ecology, Dec. 1973. <u>Industrial Waste Disposal Site Evaluation</u>.
- 5. Resource Recovery Corporation, June 11, 1973 to January 17, 1975, Monthly Waste Summaries to Washington Department of Ecology.
- 6. Personal Communication, May 27, 1987. Pat Barttels, City of Pasco Engineering Department, Engineering Technician, to Charles F. Pitz, E&E, Seattle.
- 7. Washington State Well Logs.
- 8. State of Washington Public Water Supply System Listing.
- 9. Washington State Water Rights Data.
- 10. U.S. Geological Survey Well Records.
- 11. Washington State Well Log for John Dietrich's Well located at SW 1/4, NW 1/4, Sec. 22, T9N, R30E.
- 12. U.S. Geological Survey (USGS), 1964. <u>Pasco</u>, <u>Washington</u>, Quadrangle Map, 7.5 Minute Series, Photo Revised 1973.
- 13. U.S. Geological Survey (USGS)), 1979. <u>Glade, Washington</u> Quadrangle Map, 7.5 Minute Series.
- 14. Personal Communication, May 28, 1987. Cindy Christian, Washington Department of Ecology, Eastern District Office, to Charles F. Pitz, E&E, Seattle.
- 15. Personal Communication, May 29, 1987. Jean Tomlinson to Gloria Skinner, E&E, Seattle.
- 16. Personal Communication, June 1, 1987. Don Carter, Franklin County Fire Marshall to Gloria Skinner, E&E, Seattle.
- 17. Ecology and Environment, Inc., January 1985. Preliminary Site Inspection Report of Resource Recovery Corporation, Pasco, Washington.
- 18, Personal Communication with Richard Heinemayer, 7/17/87